

SAFETY CONCERN NUMBER	SUBJECT	INITIATED BY DATE	SUPERVISOR DATE OF ANSWER	DATE REC'D BY COMM. ASSIGNED TO	COMMENTS	SETTLEMENT DATE	METHOD 1, 2, 3
86-78	Bldg. 371 - Smear counters are not being calibrated	██████████ 3/21/86	D. Hardin 3/29/86			3/29/86	1
86-79	Bldg. 123 - Water sampling during snowstorm	██████████ 4/3/86	D. Bokowski 4/17/86			4/17/86	1
86-80	Bldg. 771 - Car accident 4/2/86, East Access Road (bad weather conditions)	██████████ 4/04/86	D. Anderson 4/09/86	G. Overholt R. Chanda 04/21/86			
86-81	Bldg. 771 - Failure of Mtce. to provide welding screen on the new Line #15 3/20/86	██████████ 3/26/86	T. Larabee 4/15/86	J. Castro R. Chanda 04/21/86		5-21-88	
86-82	Bldg. 771 - Line #43, Rm. 149 moving out crusher and putting in new one	██████████ 04/08/86	R. Southall 04/15/86	G. Overholt A. Hagen 04/21/86		5-7-88	No Letter 2
86-83	Bldg. 771 - Open drum near skull line in Rm. 249	██████████ 3/21/86	E. Beck 3/27/86			03/27/86	1
86-84	Bldg. 771 - Housekeeping deteriorated until an imminent dangerous situation exists	██████████ 4/16/86	D. Baaso 4/16/86	J. Castro A. Hagen 4/21/86			