

SAFETY CONCERN NUMBER	SUBJECT	INITIATED BY DATE	SUPERVISOR DATE OF ANSWER	DATE REC'D BY COMM. ASSIGNED TO	COMMENTS	SETTLEMENT DATE	METHOD 1, 2, 3
85-124 *	Bldg. 881 - instructed to move drums prior to monitoring.	[REDACTED] 8-8-85	D. Norton 8-19-85	9/24/85 G. Overholt G. Trump			
85-125	Building 771 - Acid rain dripping from overhead in room 146-A.	[REDACTED] 6/19/85	D. Baaso 6/19/85	9/27/85 C. Noble J. SanPietro		10/21/85	2
85-126 *	Bldg. 662 - Lockout procedures not followed.	[REDACTED] 9/26/85	P. Hepner 9/27/85	10/1/85 C. Ellis G. Overholt			
85-127	Bldg. 460 - Liquid spilling out onto walk area.	[REDACTED] 8/27/85	R. Shulavik 8/27/85	10/8/85 G. Nazzise R. Chanda			
85-128 *	Bldg. 460 - Lack of protective shields at brew furnaces.	[REDACTED] 10/2/85	D. Rapier 10/2/85			10/2/85	1
85-129 *	Bldg. 771 - No access to Bldg. 715 in case of emergency.	[REDACTED] 9/21/85	R. Kamezell 9/23/85			9/23/85	1
85-130 *	Bldg. 444 - Construction area not marked - resulted in accident.	[REDACTED] 9/25/85	A. Blazon 9/30/85			9/30/85	1
85-131 *	Rad. Mon. - Downdraft rooms unsafe.	[REDACTED] 10/4/85	J. Valdez 10/7/85			10/7/85	1
85-132 *	Bldg. 444 - Acid Leak	[REDACTED] 9/10/85	J. Suder 9/10/85			10/3/85	1
85-133 *	Bldg. 444/447 - PA system inadequate.	[REDACTED] 8/28/85	J. Suder 8/30/85			10/3/85	1