

SAFETY CONCERN NUMBER	SUBJECT	INITIATED BY DATE	SUPERVISOR DATE OF ANSWER	DATE REC'D BY COMM. ASSIGNED TO	COMMENTS	SETTLEMENT DATE	METHOD 1, 2, 3
86-43	Bldg. T750P - Defective fire alarm	[REDACTED] 02/17/86	J. Hart 02/19/86	J. Castro A. Hagen 02/25/86		3/27/86	1
86-44	Bldg. 460 - Condition of coolant	[REDACTED] 02/20/86	J. Boyd P. Swenson 2/24/86	J. Castro A. Hagen 03/03/86			
86-45	Bldg. 444 - Oil in floors, can cause a fall.	[REDACTED] 02/24/86	S. Hoover 02/24/86	G. Overholt P. King 03/03/86		4/14/86	2
86-46	Bldg. 883 - Failure of Health Physics to respond to numerous requests	[REDACTED] 02/12/86	S. Thomatos 02/17/86	G. Overholt A. Fernandez 03/03/86		4/15/86	2
86-47	Bldg. 771 - Glovebox Overheat Alarm System not working, Shift Supr.'s response unsatisfactory	[REDACTED] 02/08/85	D. Anderson 08/27/85	G. Overholt A. Hagen 03/03/86		4/14/86	2
86-48	Bldg. 460 - Convex mirrors needed at intersections	[REDACTED] 01/16/86	A. Kincaid 02/25/86	J. Castro A. Fernandez 03/05/86		3/31/86	2
86-49	Bldg. 460 - Salaried Techs. refuse to wear safety glasses	[REDACTED] 2/24/86	D. Rapier 02/26/86			02/27/86	1