

SAFETY CONCERN NUMBER	SUBJECT	INITIATED BY DATE	SUPERVISOR DATE OF ANSWER	DATE REC'D BY COMM. ASSIGNED TO	COMMENTS	SETTLEMENT DATE	METHOD 1, 2, 3
86-71	Bldg.444 - Icy roads on Plantsite, access roads, and sidewalks	██████████ 03/20/86	D. Klenze 03/20/86	J. Scruggs A. Hagen 03/25/86		4-15-86	2
86-72	Bldg. 460 - Parking lot at Bldg. 460 has not been controlled by Security Dept.	██████████ 3/20/86	L. Oliver 3/20/86	J. Castro P. King 4/1/86		4-9-86	2
86-73	Bldg. 771 - No Rad. Monitor at west hallway station	██████████ 2/19/86	D. Westphal 3/12/86			3/12/86	1
86-74	Bldg. 771 - Open drum, foreman's response, crit. engr. response, Rm. 249 not mentioned in Nuclear Matl. Safety Manual	██████████ 03/21/86	E. Beck 03/27/86			03/27/86	1
86-75	Bldg. 440 - Barricading exit doors on south side a safety hazard	██████████ 02/25/86	D. John 02/27/86	J. Castro A. Fernandez 4/7/86			
86-76	Bldg. 881 - Ceiling concrete possibly falling down on personnel below	██████████ 3/25/86	J. Blair 4/7/86			04/07/86	1
86-77	Bldg. 460 - 460 parking lots were plowed, not sanded, following blizzard 4/3/86	██████████ ██████████ 4/4/86	S. Tallman 4/4/86	J. Castro A. Hagen 4/14/86			